

Final Reclamation Inspection

March 12, 2020

Operator: SCHNEIDER ENERGY SERVICES INC - 76840

Location ID: 313839

Inspection Document #: 697501210

Morgan County, CO

NENE Section 31 T5N R59W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: STROMSOE #1
Location ID: 313839



Photo 1. Photo taken of the Operator sign at location. Well was plugged and abandoned 02/13/2019.



Photo 2. Photo taken from the eastern location, facing North. Photo illustrates Operator has failed to remove all equipment from location. All equipment should have been removed by 5/13/2019. Also, all final reclamation activities should have been conducted by 5/13/2019 due to the location within cropland.

Inspection Photos
Location Name: STROMSOE #1
Location ID: 313839



Photo 3. Photo taken from the eastern location, facing Southeast. See comments under Photo 2.



Photo 4. Photo taken from the eastern location, facing South. See comments under Photo 2.

Inspection Photos
Location Name: STROMSOE #1
Location ID: 313839



Photo 5. Photo taken from the western location, facing West. See comments under Photo 2.



Photo 6. Photo taken from the western location, facing East. See comments under Photo 2.