

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402343211

Date Received:

03/15/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10454  
Name of Operator: PETROSHARE CORPORATION

Address: 9635 MAROON CIRCLE #400

City: ENGLEWOOD State: CO Zip: 80112

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Brown, Devin

(303)-349-0302

dbrown@petrosharecorp.com

Meghan Grimes

mgrimes@petrosharecorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 687400646

Inspection Date: 12/18/2018

FIR Submit Date: 12/18/2018

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: PETROSHARE CORPORATION

Company Number: 10454

Address: 9635 MAROON CIRCLE #400

City: ENGLEWOOD State: CO Zip: 80112

LOCATION - Location ID: 320350

Location Name: MARLATT-62S64W Number: 22SWNW County: \_\_\_\_\_

Qtrqr: SWN Sec: 22 Twp: 2S Range: 64W Meridian: 6  
W

Latitude: 39.863762 Longitude: -104.543620

FACILITY - API Number: 05-001- -00 Facility ID: 320350

Facility Name: MARLATT-62S64W Number: 22SWNW

Qtrqr: SWN Sec: 22 Twp: 2S Range: 64W Meridian: 6  
W

Latitude: 39.863762 Longitude: -104.543620

CORRECTIVE ACTIONS:

1 CA# 121144

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 01/17/2019

Response: CA COMPLETED

Date of Completion: 03/13/2020

Stained soiled has been cleaned up; photo attached.

Operator Comment: \_\_\_\_\_

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**2** CA# 121145

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 01/17/2019

Response: CA COMPLETED

Date of Completion: 03/13/2020

Operator Comment: Valves, pipes, and fittings have been checked and are in good mechanical condition.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: CAs have been accomplished; photos attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Meghan Grimes

Signed: \_\_\_\_\_

Title: Regulatory Manager

Date: 3/15/2020 11:01:10 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

402343212	CA Resolution Photos
-----------	----------------------

Total Attach: 1 Files