

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/05/2020

Submitted Date:

03/17/2020

Document Number:

694500182

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: NEIDEL, KRIS On-Site Inspection
 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 46290
 Name of Operator: KP KAUFFMAN COMPANY INC
 Address: 1675 BROADWAY, STE 2800
 City: DENVER State: CO Zip: 80202
Findings:

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Max Knop	303-825-4822	MKnop@kpk.com	

General Comment:

On 3/10/2020 COGCC Staff, Kris Neidel inspected spill #473059 at the Dwinell Tank Battery . Weather was overcast and 30 degrees., ice, snow and mud were all present at the time of inspection. The following was observed; Oil appeared to have over topped tanks in main battery, oil was pooled around tanks, oil flowed to the west where it ran along the secondary containment, it appeared that the oil found a burro in the ground that allowed fluid to migrate to the lower level secondary containment, Crews were using a backhoe to push fluid to a low point in the containment and vacing up free oil and water. See attached photos. Operator shall demonstrate all soils remaining are compliant with COGCC table 910-1.

Attached Documents
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500183	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5098316