

Ant Hill Unit 36-11, 36-11 BD  
API: 05-103-10392, 10393  
Inspection: 700400498



40.10471, -108.23248, 5789.7ft, 35°  
03/16/2020 10:19:52 AM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

Ant Hill Unit 36-11, 36-11 BD  
API: 05-103-10392, 10393  
Inspection: 700400498



40.10523, -108.23199, 5760.0ft, 350°  
03/16/2020 10:23:08 AM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 2. Well head.

Ant Hill Unit 36-11, 36-11 BD  
API: 05-103-10392, 10393  
Inspection: 700400498



40.10495, -108.23193, 5757.7ft, 280°  
03/16/2020 10:21:40 AM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Meter buildings & separators.**

Ant Hill Unit 36-11, 36-11 BD  
API: 05-103-10392, 10393  
Inspection: 700400498



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 4. Tanks.**