

Inspection Photos
Operator: BP America
API#: 067-06714
Date: 3/16/2020



Photo 1. View of the project area from the northeastern corner facing center. Project area is fenced. Dense kochia debris observed around the edges of the working areas.



Photo 2. View of the area in the northern project area that does not appear needed for production operations, that needs revegetation. Gray vegetation is largely weeds such as field bindweed.



Photo 3. View of the reference area, comprised of an irrigated grass field in a grazed condition.