

Inspection Photos
Location Name: Sterkel 21-1
Location ID: 320485



Pic 1 stained soil/mechanical issue

Pic 2 stained soil/mechanical issue