

Location:	Morris 13-4
Line:	Well to Treater
Technicians:	Cody Baylis
Date	10/1/2019
Time	Pressure (PSI)
10:39:50 AM	2.4
10:40:20 AM	2.5
10:40:50 AM	2.6
10:41:20 AM	2.8
10:41:50 AM	2.8
10:42:20 AM	3.1
10:42:50 AM	49.6
10:43:20 AM	57.1
10:43:50 AM	57.1
10:44:20 AM	57.1
10:44:50 AM	57.1
10:45:20 AM	57.1
10:45:50 AM	57.2
10:46:20 AM	57.2
10:46:50 AM	57.2
10:47:20 AM	57.2
10:47:50 AM	57.2
10:48:20 AM	57.2
10:48:50 AM	57.2
10:49:20 AM	57.2
10:49:50 AM	57.2
10:50:20 AM	57.2
10:50:50 AM	57.2
10:51:20 AM	57.2
10:51:50 AM	57.3
10:52:20 AM	57.3
10:52:50 AM	57.3
10:53:20 AM	57.3
10:53:50 AM	57.3
10:54:20 AM	57.3
10:54:50 AM	57.3
10:55:20 AM	57.3
10:55:50 AM	57.4
10:56:20 AM	57.4
10:56:50 AM	57.4
10:57:20 AM	57.4
10:57:50 AM	57.4
10:58:20 AM	57.4
10:58:50 AM	57.4
10:59:20 AM	57.4
10:59:50 AM	57.4
11:00:20 AM	57.4

11:00:50 AM	57.4
11:01:20 AM	57.4
11:01:50 AM	57.4
11:02:20 AM	57.4
11:02:50 AM	57.4
11:03:20 AM	57.4
11:03:50 AM	57.5
11:04:20 AM	57.5
11:04:50 AM	57.5
11:05:20 AM	57.5
11:05:50 AM	57.5
11:06:20 AM	57.5
11:06:50 AM	57.5
11:07:20 AM	57.5
11:07:50 AM	57.5
11:08:20 AM	57.5
11:08:50 AM	57.5
11:09:20 AM	57.6
11:09:50 AM	57.5
11:10:20 AM	57.6
11:10:50 AM	57.6
11:11:20 AM	57.6
11:11:50 AM	57.6
11:12:20 AM	57.6
11:12:50 AM	57.6
11:13:20 AM	57.6
11:13:50 AM	57.6
11:14:20 AM	57.6
11:14:50 AM	57.6
11:15:20 AM	57.6
11:15:50 AM	57.6
11:16:20 AM	57.6
11:16:50 AM	57.6
11:17:20 AM	57.7
11:17:50 AM	57.7
11:18:20 AM	0
11:18:50 AM	1.2
11:19:20 AM	2.2
11:19:50 AM	0
11:20:20 AM	0

Pass/Fail

% loss over 30 minutes	0.00%	Less than 10%	Yes		
% loss in last 5 minutes	0.17%	Less than 1%	Yes		Pass

