

Location:	Sarti 24-10
Line:	Flowline - Tubing
Technicians:	Cody Baylis
Date	10/1/2019
Time	Pressure (PSI)
2:19:20 PM	5
2:19:50 PM	5.1
2:20:20 PM	5.2
2:20:50 PM	5.4
2:21:20 PM	0
2:21:50 PM	60.6
2:22:20 PM	60.5
2:22:50 PM	60.4
2:23:20 PM	60.4
2:23:50 PM	60.3
2:24:20 PM	60.2
2:24:50 PM	60.2
2:25:20 PM	60.1
2:25:50 PM	60
2:26:20 PM	59.9
2:26:50 PM	59.9
2:27:20 PM	59.9
2:27:50 PM	59.8
2:28:20 PM	59.8
2:28:50 PM	59.8
2:29:20 PM	59.8
2:29:50 PM	59.8
2:30:20 PM	59.7
2:30:50 PM	59.7
2:31:20 PM	59.7
2:31:50 PM	59.7
2:32:20 PM	59.6
2:32:50 PM	59.6
2:33:20 PM	59.6
2:33:50 PM	59.6
2:34:20 PM	59.6
2:34:50 PM	59.6
2:35:20 PM	59.6
2:35:50 PM	59.6
2:36:20 PM	59.5
2:36:50 PM	59.5
2:37:20 PM	59.5
2:37:50 PM	59.5
2:38:20 PM	59.5
2:38:50 PM	59.5
2:39:20 PM	59.5
2:39:50 PM	59.5

2:40:20 PM	59.5
2:40:50 PM	59.5
2:41:20 PM	59.5
2:41:50 PM	59.4
2:42:20 PM	59.4
2:42:50 PM	59.3
2:43:20 PM	59.3
2:43:50 PM	59.2
2:44:20 PM	59.2
2:44:50 PM	59.2
2:45:20 PM	59.2
2:45:50 PM	59.2
2:46:20 PM	59.2
2:46:50 PM	59.2
2:47:20 PM	59.2
2:47:50 PM	59.2
2:48:20 PM	59.2
2:48:50 PM	59.2
2:49:20 PM	59.2
2:49:50 PM	59.2
2:50:20 PM	59.2
2:50:50 PM	59.2
2:51:20 PM	59.2
2:51:50 PM	59.2
2:52:20 PM	59.2
2:52:50 PM	0.3
2:53:20 PM	2.1
2:53:50 PM	3.1
2:54:20 PM	3.8
2:54:50 PM	4.3
2:55:20 PM	4.8

Pass/Fail

% loss over 30 minutes	2.31%	Less than 10%	Yes		
% loss in last 5 minutes	0.00%	Less than 1%	Yes		Pass

