

Inspection Photos

API: 071-07915

Operator: WAPITI OPERATING LLC

Inspection Date: 3/17/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07915 | Date: 3/17/2020

Inspection Photos



Photo 1. Facing southwest along the main lease road. The road has recently been graded and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 3/17/2020

Inspection Photos



Photo 2. Facing west along the main road ascends the hill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 3/17/2020

Inspection Photos



Photo 3. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 3/17/2020

Inspection Photos



Photo 4. Facing southwest toward the cut slope. This area is bare of vegetation and needs to be monitored and reseeded as needed for revegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 3/17/2020