

Inspection Photos

API: 071-09060

Operator: WAPITI OPERATING LLC

Inspection Date: 3/17/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09060 | Date: 3/17/2020

Inspection Photos



Photo 1. Facing west along the main lease road. The road has been graded and is maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09060 | Date: 3/17/2020

Inspection Photos



Photo 2. There are several water bars installed along the main lease road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09060 | Date: 3/17/2020

Inspection Photos



Photo 3. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09060 | Date: 3/17/2020