

Inspection Photos
Location Name: LD 12 Tank Battery
Location ID: 437863



Photo 1 – Tank Battery



Photo 2 – Tank Battery

Inspection Photos
 Location Name: LD 12 Tank Battery
 Location ID: 437863



Photo 3 – Tank Battery Signs

Photo 4 – Tank Battery Signs

Inspection Photos
Location Name: LD 12 Tank Battery
Location ID: 437863



Photo 5 – Northside Water Tanks, Content and Capacity fading, no longer visible

Photo 6 – Northside Water Tanks, Content and Capacity missing

Inspection Photos
Location Name: LD 12 Tank Battery
Location ID: 437863



Photo 7 – Southside Water Tanks, Content and Capacity missing on all Tanks



Photo 8 – Unmarked Risers at NW shed

Inspection Photos
Location Name: LD 12 Tank Battery
Location ID: 437863




Photo 9 – Unused Supply, Stained Soil and Unmarked 2” Risers at 2-Phase at I.A. Shed



Photo 10 – Unused Compressor curtains/covers

Inspection Photos
Location Name: LD 12 Tank Battery
Location ID: 437863



Photo 11 – Trash Dumpster not covered, overflowing. Trash all along the East, Southeast and South sides of the Location



Photo 12 – Trash all along the East, Southeast and South sides of the Location

Inspection Photos
Location Name: LD 12 Tank Battery
Location ID: 437863



Photo 13 – Trash all along the East, Southeast and South sides of the Location




Photo 14 – Trash all along the East, Southeast and South sides of the Location

Inspection Photos
Location Name: LD 12 Tank Battery
Location ID: 437863



Photo 15 – Trash all along the East, Southeast and South sides of the Location



Photo 16 – Trash all along the East, Southeast and South sides of the Location

Inspection Photos
Location Name: LD 12 Tank Battery
Location ID: 437863



Photo 17 – Trash all along the East, Southeast and South sides of the Location




Photo 18 – Trash all along the East, Southeast and South sides of the Location

Inspection Photos
Location Name: LD 12 Tank Battery
Location ID: 437863



Photo 19 – Trash all along the East, Southeast and South sides of the Location



Photo 20 – Unused Chemical Tanks and stands. Trash