

Inspection Photos

Location Name: VPR C NO. 35 CA 4-18-20

API#: 05-071-06957

INSP. #: 695102337



Colorado Oil & Gas Conservation Commission
37.03323, -104.78571, 2338.0m, 215°
2020/03/18 11:48:56

PHOTO 1: LOCATION



Colorado Oil & Gas Conservation Commission
37.03331, -104.78619, 2334.0m, 212°
2020/03/18 11:49:39

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: VPR C NO. 35 CA 4-18-20

API#: 05-071-06957

INSP. #: 695102337



PHOTO 3: THERE IS AN AREA APP. 3' IN DIAMETER OF IMPACTED SOIL APPEARS TO BE COMING FROM POLISH ROD OILER. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 4-18-20.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources