

Inspection Photos  
Operator: PO&G Operating LLC  
Lease: Beeson 3-21  
Facility ID/API # 05-063-06257



1. Lease sign by Tanks

2. Battery Equipment.

**Inspection Photos**  
**Operator: PO&G Operating LLC**  
**Lease: Beeson 3-21**  
**Facility ID/API # 05-063-06257**



**1. Tanks with Manhole covers removed**



**2. Battery without berms**

**Inspection Photos**  
**Operator: PO&G Operating LLC**  
**Lease: Beeson 3-21**  
**Facility ID/API # 05-063-06257**



**5. Well site, Wellhead and Pumping Unit removed**

**6. Rods**

**Inspection Photos**  
**Operator: PO&G Operating LLC**  
**Lease: Beeson 3-21**  
**Facility ID/API # 05-063-06257**



**7. Chemical Tanks & Barrels**

**8. Electric panel and Cathodic Rectifier**