

HALLIBURTON

iCem[®] Service

CONFLUENCE DJ LLC-EBUS

Date: Thursday, December 19, 2019

WALLA 5-10-4L

SURFACE

Job Date: Saturday, December 14, 2019

Sincerely,

SAM CARPENTER

Legal Notice

Disclaimer:

All information in this report is provided subject to the terms and conditions which govern the services provided by Halliburton. Halliburton personnel use their best efforts in gathering information and their best judgment in interpreting it, but any interpretation, research, analysis or recommendation furnished by Halliburton are opinions based upon inferences from measurements and empirical relationships and assumptions, which inferences and empirical relationships and assumptions are not infallible, and with respect to which professionals in the industry may differ. iCem 3D Displacement results are used to understand how fluids intermix during a cement job. Simulation and 3D displacement results are not intended as and should not be used as a replacement for bond logs in determining top of cement. Current 3D model calculations are known to model more volume than the input volume for standard cases due to known calculation improvements required. For rotational cases, the modeled volume will be impacted by the same calculations impacting the standard cases, as well as additional constraints imposed to make the calculation time required operationally feasible. Therefore, until further notice, 3D displacement results should not be used for replacement of a bond log, or used as an identifier of top of cement. HALLIBURTON IS UNABLE TO GUARANTEE THE ACCURACY OF ANY CHART INTERPRETATION, RESEARCH ANALYSIS, OR JOB RECOMMENDATION and any interpretation or recommendation is not for use of or reliance upon by any third party. The customer has full responsibility for any of its decisions which are based on the information provided in this report.

Table of Contents

1.0	Cementing Job Summary	4
1.1	Executive Summary	4
2.0	Real-Time Job Summary	7
2.1	Job Event Log	7
3.0	Attachments.....	10
3.1	CONFLUENCE WALLA 5-10-4L SURFACE-Custom Results.png	10

1.0 Cementing Job Summary

1.1 Executive Summary

Halliburton appreciates the opportunity to perform the cementing services on the **Walla 5-10-4L cement Surface** casing job. A pre-job safety meeting was held before the job where details of the job were discussed, potential safety hazards were reviewed, and environmental compliance procedures were outlined.

Approximately 41 bbls of cement were returned to surface.

Halliburton maintains a continuous quality improvement process and appreciates any comments or suggestions that you may have. Halliburton again thanks you for the opportunity to perform service work on this well. We hope to be your solutions provider for future projects.

Respectfully,

Halliburton Fort Lupton

The Road to Excellence Starts with Safety

Sold To #: 375989	Ship To #: 3851312	Quote #:	Sales Order #: 0906163047
Customer: CONFLUENCE DJ LLC-EBUS		Customer Rep: BRYAN	
Well Name: WALLA		Well #: 5-10-4L	API/UWI #: 05-123-46223-00
Field: WATTENBERG	City (SAP): HUDSON	County/Parish: WELD	State: COLORADO
Legal Description: SE SE-31-1N-65W-861FSL-705FEL			
Contractor: ENSIGN DRLG		Rig/Platform Name/Num: ENSIGN 122	
Job BOM: 7521 7521			
Well Type: HORIZONTAL OIL			
Sales Person: HALAMERICA/H171328		Srvc Supervisor: Lance Carpenter	

Job

Formation Name			
Formation Depth (MD)	Top	Bottom	
Form Type	BHST		
Job depth MD	1543ft	Job Depth TVD	1543
Water Depth		Wk Ht Above Floor	3
Perforation Depth (MD)	From	To	

Well Data

Description	New / Used	Size in	ID in	Weight lbm/ft	Thread	Grade	Top MD ft	Bottom MD ft	Top TVD ft	Bottom TVD ft
Casing		9.625	8.921	36			0	1543	0	
Open Hole Section			13.5				0	1570		

Tools and Accessories

Type	Size in	Qty	Make	Depth ft	Type	Size in	Qty	Make
Guide Shoe	9.625			1543	Top Plug	9.625	1	HES
Float Shoe	9.625				Bottom Plug	9.625		HES
Float Collar	9.625			1498	SSR plug set	9.625		HES
Insert Float	9.625				Plug Container	9.625	1	HES
Stage Tool	9.625				Centralizers	9.625		HES

Fluid Data

Stage/Plug #: 1										
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	
1	Mud Flush III (Powder)	Mud Flush III	40	bbl	8.4			8		
42 gal/bbl		FRESH WATER								

Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
2	13.5# SwiftCem	SWIFTCEM (TM) SYSTEM	650	sack	13.5	1.74		8	9.17
9.17 Gal		FRESH WATER							

Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
3	Displacement fluid		116	bbl	8.3			8	

Cement Left In Pipe	Amount	44 ft	Reason	Shoe Joint
Mix Water:	pH ##	Mix Water Chloride:## ppm	Mix Water Temperature:## °F °C	
Cement Temperature:## °F °C	Plug Displaced by:## lb/gal kg/m3 XXXX	Disp. Temperature:## °F °C		
Plug Bumped?Yes	Bump Pressure:530 psi	Floats Held?Yes		
Cement Returns:41 bbl	Returns Density:## lb/gal kg/m3	Returns Temperature:## °F °C		

Comment

JOB WENT WELL. PERFORMED AS DESIGNED. SLURRY WAS WEIGHED BY PRESSURIZED MUD BALANCE AND VOLUME VERIFIED BY MIX FLUID. PUMPED MUD FLUSH SPACER WITH RED DYE IN FIRST 10 BBL. DROPPED TOP PLUG AFTER CEMENT. SPACER TO SURFACE AT 35 AWAY. CEMENT TO SURFACE AT 75 BBL AWAY. PLUG BUMPED WITH 530 PSI AT 3.5 BPM. FLOATS HELD WITH ½ BBL BACK.

40 BBL SPACER TO SURFACE
 41 BBL CEMENT TO SURFACE
 TOP OF CEMENT AT SURFACE

2.0 Real-Time Job Summary

2.1 Job Event Log

Type	Seq. No.	Activity	Graph Label	Date	Time	Source	PS Pump Press <i>(psi)</i>	DH Density <i>(ppg)</i>	Comb Pump Rate <i>(bbl/min)</i>	Pump Stg Tot <i>(bbl)</i>	Comments
Event	1	Call Out	Call Out	12/13/2019	17:30:00	USER					CREW CALLED OUT. ON LOCATION 2330
Event	2	Depart Shop for Location	Depart Shop for Location	12/13/2019	21:00:00	USER					CREW HAS VERIFIED EQUIPMENT AND MATERIALS FOR THE JOB AND DEPARTS AFTER HAVING JOURNEY MANAGEMENT SAFETY MEETING DISCUSSING ROUTE, CONVOY ORDER, FOLLOWING DISTANCE, HAZARDS, CONSTRUCTION, DRIVING TO CONDITIONS AND COMMUNICATION
Event	3	Arrive At Loc	Arrive At Loc	12/13/2019	21:30:00	USER					CREW ARRIVES AT LOCATION. RIG JUST TD'ING THE WELL. MOVED CREW TO NEXT LOCATION OVER TO SAVE SPACE
Event	4	Casing on Bottom	Casing on Bottom	12/14/2019	03:15:00	USER					CASING ON BOTTOM. CREW CAN NOW SPOT IN EQUIPMENT AND BEGIN RIGGING UP LINES
Event	5	Safety Meeting	Safety Meeting	12/14/2019	03:45:00	USER	-1.00	2.42	0.00	1.30	CREW, RIG CREW AND CUSTOMER REP HAVE PRE JOB SAFETY MEETING DISCUSSING HAZARDS, MUSTER AREAS, LINE OF FIRE, PRESSURE HAZARDS, RED ZONES, PINCH POINTS, TUGGER OPERATIONS,

CONTINGENCIES,
 COMMUNICATION AND
 STOP WORK AUTHORITY

Event	6	Check Floats	Start Job	12/14/2019	04:06:44	COM4	-1.00	2.42	0.00	1.30	START JOB
Event	7	Test Lines	Test Lines	12/14/2019	04:21:27	COM4	70.00	8.32	0.00	25.50	FILL LINES WITH 3 BBL WATER. PRESSURE TEST HES LINES TO 3000 PSI AND HELD FOR A FEW MINUTES. TEST GOOD
Event	8	Pump Spacer 1	Pump Spacer 1	12/14/2019	04:26:52	COM4	5.00	8.27	0.00	0.00	PUP 40 BBL MUD FLUSH SPACER WITH RED DYE IN FIRST 10 BBL
Event	9	Pump Lead Cement	Pump Lead Cement	12/14/2019	04:41:03	COM4	109.00	8.64	4.00	0.00	PUMP 201 BBL SWIFTCEM 13.5# 1.74 YIELD 9.17 GAL 650 SACKS
Event	10	Drop Top Plug	Drop Top Plug	12/14/2019	05:25:02	COM4	-25.00	12.92	0.00	230.60	DROP TOP PLUG
Event	11	Pump Displacement	Pump Displacement	12/14/2019	05:25:14	COM4	-25.00	12.92	0.00	230.60	PUMP 116 BBL WATER DISPLACEMENT WASHING UP ON TOP OF THE PLUG
Event	12	Bump Plug	Bump Plug	12/14/2019	05:53:20	COM4	749.00	8.28	0.00	123.80	BUMP PLUG AT 3.5 BPM AT 530 PSI FINAL CIRCULATING PRESSURE. TOOK TO 850 PSI
Event	13	Check Floats	Check Floats	12/14/2019	05:56:22	USER	793.00	8.27	0.00	123.80	CHECK FLOATS. FLOATS HELD WITH 0.5 BBL BACK
Event	14	End Job	End Job	12/14/2019	06:01:37	COM4	-23.00	8.26	0.00	128.50	END JOB
Event	15	Safety Meeting	Safety Meeting	12/14/2019	06:05:00	USER	-23.00	8.27	9.00	155.00	CREW HAS PRE RIG DOWN SAFETY MEETING DISCUSSING PINCH POINTS, SLIPS TRIPS FALLS, LINE OF FIRE, TUGGER OPERATIONS, RIG OPERATIONS, TEAM LIFTING, COMMUNICATION,

HAND PLACEMENT AND
BEGIN RIGGING DOWN
EQUIPMENT AND LINES

Event	16	Depart Location	Depart Location	12/14/2019	08:00:00	USER
-------	----	-----------------	-----------------	------------	----------	------

CREW IS RIGGED DOWN
AND READY TO DEPART
AFTER HAVING JOURNEY
MANAGEMENT SAFETY
MEETING DISCUSSING
HOURS OF SERVICE, FIT FOR
DUTY, DIRECTIONS,
COMMUNICATION AND
WALK AROUNDS

3.0 Attachments

3.1 CONFLUENCE WALLA 5-10-4L SURFACE-Custom Results.png



