

Coal Draw 2
API: 05-103-07184
Inspection: 700400522



40.06846, -108.8084, 5345.4ft, 32°
03/17/2020 05:14:47 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Coal Draw 2
API: 05-103-07184
Inspection: 700400522



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pump jack.

Coal Draw 2
API: 05-103-07184
Inspection: 700400522



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Tank.

Coal Draw 2
API: 05-103-07184
Inspection: 700400522



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Well head.

Coal Draw 2
API: 05-103-07184
Inspection: 700400522

venting



40.06855, -108.80816, 5339.9ft, 293°

03/17/2020 05:16:00 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Well head cellar.