



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Mar 9, 2020 5:00:23 PM MDT
Server Receive Date:	Mar 9, 2020 5:03:16 PM MDT
Reference Number:	20200309-18135840776
Location:	557 Airpark Dr, Durango, CO 81303, USA Mar 9, 2020 5:02:43 PM MDT [View Map]

Information

Name	colen@horizonenvservices.com
Date	Dec 17, 2019
Well Name	HANCOCK GAS UNIT 1
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions

Photo of first corrective action completed



Completed work description Corrective Action 1 sign

Photo of second corrective action completed



Completed work description of corrective action 2 trash picked up

Completed work description of corrective action 3 na

Completed work description na

Completed work description of corrective action 4
Completed work description
Summary of all work completed

na
trash removed
trash removed