

Final Reclamation Inspection

March 12, 2020

Operator: BATES* JAMES EDWARD - 6575

API #: 05-001-06796

Inspection Document #: 697501245

Adams County, CO

SESE Section 7 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: WIERMAN #1
API #: 05-001-06796



Photo 1. Photo taken from the tank battery, facing Northwest. Photo illustrates tank battery has been recently cultivated. COGCC staff will conduct a future inspection during the active growing season to evaluate vegetative compliance.

Inspection Photos
Location Name: WIERMAN #1
API #: 05-001-06796



Photo 2. Photo taken from the tank battery, facing North. See comments under Photo 1.

Inspection Photos
Location Name: WIERMAN #1
API #: 05-001-06796



Photo 3. Photo taken from the tank battery, facing Northeast. See comments under Photo 1.