



Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Mar 13, 2020 8:03:14 AM MDT
Server Receive Date:	Mar 13, 2020 8:06:47 AM MDT
Reference Number:	20200313-18136223621
Location:	557 Airpark Dr, Durango, CO 81303, USA Mar 13, 2020 8:05:05 AM MDT [ <a href="#">View Map</a> ]

Information

Name	colen@horizonenvservices.com
Date	Mar 12, 2020
Well Name	BONDS GAS UNIT 3E
API Number	50670666700
Select State	Colorado
Work type	Plug & Abandonment Work
Action Complete	Compliance Inspection Actions Seeding Erosion Repairs Install Rock Run Down Clean Up Weed Debris Spot seeding

Photo of first corrective action completed



Completed work description Corrective Action 1  
Photo of second corrective action completed

Seeded, mulched and installed ECB.



Completed work description of corrective action 2

Built silt trap with rock rundown. Seeded, mulched and installed ECB.

Photo of third corrective action completed



Completed work description of corrective action 3

Seeded and mulched heavily disturbed areas from Red Cedar work.

Photo of fourth corrective action completed



Completed work description

Seeded and installed ECB on cut slope.

Completed work description of corrective action 4

Seeded and mulched heavily disturbed areas, removed well sign, cleaned up weed debris, installed silt trap with a rock rundown. The rock was hand picked on location.

Additional photos



Additional photos



Additional photos



Additional photos



Additional photos



Completed work description

Seeded and mulched heavily disturbed areas, removed well sign, cleaned up weed debris, installed silt trap with a rock rundown. The rock was hand picked on location.

Summary of all work completed

Seeded and mulched heavily disturbed areas, removed well sign, cleaned up weed debris, installed silt trap with a rock rundown. The rock was hand picked on location.