

Inspection Photos

API: 071-09237

Operator: TIMBER CREEK OPERATING

Inspection Date: 3/19/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09237 | Date: 3/19/2020

Inspection Photos



Photo 1. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09237 | Date: 3/19/2020

Inspection Photos



Photo 2. There is a water leak coming from the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09237 | Date: 3/19/2020

Inspection Photos



Photo 3. There is oil on the engine skid and on soil that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09237 | Date: 3/19/2020

Inspection Photos



Photo 4. There is staining coming from the tank. The lid is open and appear which appears to have spilled out of.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09237 | Date: 3/19/2020

Inspection Photos



Photo 5. There is oil on the engine skid and on soil that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09237 | Date: 3/19/2020