

Inspection Photos
Location Name: RMV 152-22
Location ID: 335193 & Spill/Release ID: 446837
Inspection Date: March 17, 2020



Location sign.



**View of the dump lines and separators looking northeast.
Unmarked riser located in the red circle.**



Inspection Photos

Location Name: RMV 152-22

Location ID: 335193 & Spill/Release ID: 446837

Inspection Date: March 17, 2020



View of the dump lines and separators looking southwest.

