

**Inspection Photos**  
**Location Name: Open Range 18**  
**Location ID: 447512**



**Photo 1. Overview of workover on location taken facing northeast.**



**Photo 2. Some wellhead signs knocked over.**

