

**Inspection Photos**  
**Location Name: Coalmont 3-13H**  
**Location ID: 421227**



**Photo 1. Overview of location taken facing south.**



**Photo 2. Container at wellhead without secondary containment.**

