

Inspection Photos

Operator: Logos Operating
API#: 067-08097 Date:
3/16/2020



Photo 1. View of the project area from the northern edge facing center.



Photo 2. View of the eastern project area. Revegetation remains sparse in portions, progressing within grasses such as western wheatgrass, blue grama, and crested wheatgrass.



Photo 3. View of the northwestern cut-slope. Hydromulch and wattle on slope. Revegetation progressing in portions and remains sparse in other portions. Needs to be monitored during the 2020 growing season and if not progressing then additional measures will be needed.



Photo 4. View of the reference area, comprised of open pinyon-juniper woodland with sagebrush and herbaceous understory.