

Inspection Photos
Operator: BP America
API#: 067-06571
Date: 3/18/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of farm equipment stored within the interim reclamation area.



Photo 3. View of the western project area from the southwestern corner facing northward. Revegetation is progressing, largely with smooth brome.



Photo 4. View of the surrounding reference area comprised of irrigated grass field.