

Inspection Photos

Location Name: RMV 152-22

Location ID: 335193 & Spill/Release ID: 437202

Inspection Date: March 17, 2020



Location sign.



Tank battery looking east, 2 80 bbl Produced Water steel ASTs and a 200 bbl Condensate steel AST.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: RMV 152-22

Location ID: 335193 & Spill/Release ID: 437202

Inspection Date: March 17, 2020



200 bbl Condensate steel AST.



Tank battery looking west



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources