

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/16/2020

Submitted Date:

03/16/2020

Document Number:

701000249

**FIELD INSPECTION FORM**

Loc ID 304121 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
254095	WELL	SI	01/01/2020	GW	125-07973	BRENNER 42-26	PR

**General Comment:**

Routine Inspection

### Location

<b>Lease Road:</b>			
Type	Access		
comment:	Trail through farm ground		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Add sign at water tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign mounted to fence at unit		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:		
Corrective Action:		Date: _____

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Metal fence around water tank		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal fence around unit, wellhead, meter shed and metal box		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:	Jensen unit		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator in metal box		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Gas scrubber and bellows meter (for domestic use) and gas scrubber for prime mover		
Corrective Action:		Date:	

Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	Arrow gas engine	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		39.684120,-102.253240
Comment:	Fiberglass open top water tank 50% buried by HWY 385				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	210bbbs
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

<b>Inspected Facilities</b>				
Facility ID: 254095	Type: WELL	API Number: 125-07973	Status: SI	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing. Casing production			
Corrective Action:				Date:

--	--	--	--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Other	Pass			

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT