

Inspection Photos

API#045-07455

Operator: Terra

Inspection Number: 692402017

Inspection Date: 3/18/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northwest.

March 18, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra PA Knight API#045-07455



Photo#2:
Anchors remain on Location.



Photo#3:
Anchors remain on Location..

March 18, 2020



Photo#4:
Site is weedy with Noxious and Ruderal weeds

Photo#5:
Site appears Compacted.

March 18, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra PA Knight API#045-07455



Photo#6:
Open Valve Cans.

March 18, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#7:
Open Valve Cans.

Inspection Photos: Terra PA Knight API#045-07455



Photo#8:
Former Equipment area.

March 18, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra PA Knight API#045-07455



Photo#9:
Miscellaneous equipment/debris.



Photo#10:
Miscellaneous equipment/debris.

March 18, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra PA Knight API#045-07455