

**Inspection Photos**  
**Location Name: Rohn State LD03-65-1HN Multi/Tank Batter**  
**Location ID: 433076**



**Photo 1 – Tank Battery**



**Photo 2 – Signage**



## Inspection Photos

Location Name: Rohn State LD03-65-1HN Multi/Tank Batter

Location ID: 433076



Photo 3 – East Wellheads



Photo 4 – Signage





## Inspection Photos

Location Name: Rohn State LD03-65-1HN Multi/Tank Batter

Location ID: 433076



Photo 5 – West Wellheads



Photo 6 – Signage



## Inspection Photos

Location Name: Rohn State LD03-65-1HN Multi/Tank Batter

Location ID: 433076



**Photo 7 – Chemical Label has faded at West Wellheads**



**Photo 8 – Chemical Label has faded at West Wellheads**



## Inspection Photos

Location Name: Rohn State LD03-65-1HN Multi/Tank Batter

Location ID: 433076



**Photo 9 – Unused Automation wires at South Gas Lift Meter Houses**



**Photo 10 – Unused Walkover stairs West of Oil Tanks**

## Inspection Photos

Location Name: Rohn State LD03-65-1HN Multi/Tank Batter

Location ID: 433076



**Photo 11 – Unused Chemical Tank and Stands**



**Photo 12 – Water Tank – Signage missing**



## Inspection Photos

Location Name: Rohn State LD03-65-1HN Multi/Tank Batter

Location ID: 433076



Colorado Oil and Gas Conservation Commission  
40.77667, -103.86071, 4650.7ft, 292°  
03/19/2020 12:39:03

**Photo 13 – Water Tanks – Signage missing**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources