

# Inspection Photos

API: 071-08273

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 3/23/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-08273 | Date: 3/23/2020

## Inspection Photos



**Photo 1.** Facing northeast along the access road which has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08273 | Date: 3/23/2020



## Inspection Photos



**Photo 2.** Facing northeast along the access road toward the location. The access road is elevated from the surrounding topography.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08273 | Date: 3/23/2020



## Inspection Photos



**Photo 3.** Facing northeast toward the fill and cut slope of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08273 | Date: 3/23/2020



## Inspection Photos



**Photo 4.** Facing toward the cut slope which is approximately 25 feet.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08273 | Date: 3/23/2020



## Inspection Photos



**Photo 5.** Facing southeast toward the cut slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08273 | Date: 3/23/2020



## Inspection Photos



**Photo 6.** Facing east at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08273 | Date: 3/23/2020



## Inspection Photos



**Photo 7.** Facing back to the southwest at the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08273 | Date: 3/23/2020