

Inspection Photos

API: 071-09685

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/23/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09685 | Date: 3/23/2020

Inspection Photos



Photo 1. The erosion observed during previous inspection along the pre-existing road has been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 3/23/2020

Inspection Photos



Photo 2. The erosion has been repaired and water bars have been installed along the road. Water bar is installed at red line.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 3/23/2020

Inspection Photos



Photo 3. The sediment traps along the access road have been maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 3/23/2020

Inspection Photos



Photo 4. Facing west along the pre-existing access road. Water bar is installed at this point in the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 3/23/2020

Inspection Photos



Photo 5. Facing southeast at the beginning of the access road. Operator sign will need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 3/23/2020

Inspection Photos



Photo 6. Facing southeast along the reclaimed access road. Perennial vegetation has uniformly established along the reclaimed road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 3/23/2020

Inspection Photos



Photo 7. Facing southeast toward the location



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 3/23/2020

Inspection Photos



Photo 8. Facing northeast. Vehicle ruts are across the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 3/23/2020

Inspection Photos



Photo 9. Facing northwest toward the location. Perennial vegetation is uniformly established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 3/23/2020

Inspection Photos



Photo 10. Facing southeast toward the location. Perennial vegetation is uniformly established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 3/23/2020