

RG 11-7-397
API: 05-103-11060
Inspection: 700400622



39.80788, -108.33025, 6700.5ft, 18°
03/23/2020 02:07:58 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

RG 11-7-397
API: 05-103-11060
Inspection: 700400622



39.80789, -108.3302, 6701.1ft, 341°
03/23/2020 02:08:21 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well head.

RG 11-7-397
API: 05-103-11060
Inspection: 700400622



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Separator.

RG 11-7-397
API: 05-103-11060
Inspection: 700400622



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Tanks.