

RG 24-13-398  
API: 05-103-10702  
Inspection: 700400626



39.78384, -108.34356, 7016.0ft, 2°  
03/23/2020 02:21:37 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

RG 24-13-398  
API: 05-103-10702  
Inspection: 700400626



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Separator.**



RG 24-13-398  
API: 05-103-10702  
Inspection: 700400626



39.78444, -108.34331, 7027.9ft, 98°  
03/23/2020 02:24:55 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 3. Tanks.

RG 24-13-398  
API: 05-103-10702  
Inspection: 700400626



39.78401, -108.34399, 7020.3ft, 48°  
03/23/2020 02:22:48 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 4. Cattle water tank on edge of location.**