

Figure Four A16 498  
API: 05-103-10737, 10738  
Inspection: 700400630



39.70618, -108.39107, 8143.8ft, 2°  
03/23/2020 03:15:17 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 1. Location.

Figure Four A16 498  
API: 05-103-10737, 10738  
Inspection: 700400630



Figure Four A16 498  
API: 05-103-10737, 10738  
Inspection: 700400630



Figure Four A16 498  
API: 05-103-10737, 10738  
Inspection: 700400630



39.70672, -108.3911, 8159.4ft, 90°  
03/23/2020 03:10:20 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 4. Tanks.



Inspection: 700400630




Figure Four A16 498  
API: 05-103-10737, 10738  
Inspection: 700400630

