

Figure Four J11 498
API: 05-103-10519
Inspection: 700400638



39.71587, -108.35585, 7801.9ft, 235°
03/23/2020 04:29:28 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Figure Four J11 498
API: 05-103-10519
Inspection: 700400638



39.71577, -108.35596, 7794.9ft, 339°
03/23/2020 04:28:32 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well head.

Figure Four J11 498
API: 05-103-10519
Inspection: 700400638



39.71563, -108.35609, 7793.8ft, 274°

03/23/2020 04:26:14 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Separator.

Figure Four J11 498
API: 05-103-10519
Inspection: 700400638



Figure Four J11 498
API: 05-103-10519
Inspection: 700400638



39.71588, -108.3559, 7801.7ft, 50°
03/23/2020 04:29:00 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Unknown?