

Inspection Photos
Location Name: Phelps 1-13
Location ID: 319627



Colorado Oil And Gas Conservation Commission
40.30491, -104.81641, 1430.0m
03/24/2020 9:43:09 AM

Production facility

Inspection Photos
Location Name: Phelps 1-13
Location ID: 319627



Trash on 1/13/2020



Trash on 3/24/2020

Inspection Photos
Location Name: Phelps 1-13
Location ID: 319627



Trash on 1/13/2020



Trash on 3/24/2020

Inspection Photos
Location Name: Phelps 1-13
Location ID: 319627



Trash on 1/13/2020



Trash on 3/24/2020

Inspection Photos
Location Name: Phelps 1-13
Location ID: 319627



Trash on 1/13/2020



Trash on 3/24/2020

Inspection Photos
Location Name: Phelps 1-13
Location ID: 319627



Trash on 1/13/2020



Trash on 3/24/2020