

Inspection Photos
Location Name: HSR-Guttersen 15-28
Location ID: 330479



Photo #1 Well & Sign



Photo #2 Variance Tag

Inspection Photos
Location Name: HSR-Guttersen 15-28
Location ID: 330479



Photo #3 Tank Battery



Photo #4 Separator & Meter Run

Inspection Photos
Location Name: HSR-Guttersen 15-28
Location ID: 330479



Photo #5 ECD



Photo #6 Inadequate berm floor/wall

Inspection Photos
Location Name: HSR-Guttersen 15-28
Location ID: 330479



Photo #7 Inadequate berm floor/wall



Photo #8 Inadequate berm floor/wall