

Inspection Photos
Location Name: SWEDEN 21-2
API#: 05-071-09557
INSP. #: 695102347



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos
 Location Name: SWEDEN 21-2
 API#: 05-071-09557
 INSP. #: 695102347

Calibration Report

Report Date: 1/16/20 10:15 AM Collection Time: 1/18/20 10:13 AM

Device ID: 100109557 System: Contact # 719-846-7898

Location: Sweden 21-2 Field: Raton Basin

State: Colorado

Producer: Evergreen Natural Resources

Purchaser: Colorado Interstate Gas

Check 2: Calibration

Current Plate Size: 0.375 Tap Type: Flange Specific Gravity: 0.566

Pipe Size: 2.065 SP Tap Location: Up Stream

Atmos. Pressure: 14.73 Temperature Bias: 0

Pressure Base: 14.73 Temperature Bias: 0

Plate Inspected? Yes No Dirty Yes No Nipped? Yes No

Edges Sharp? Yes No Plate M'd Yes No Warped? Yes No

Seal Ring Damaged? Yes No Pitted Yes No Bevel Downstream Yes No

Check 3: Calibration Data

DIFFERENTIAL				TEMPERATURE			
FOUND	LEI	TEMP	LEI	FOUND	LEI	TEMP	LEI
6.00	0.54	0.00	0.00	111.25	111.25	111.25	111.25
99.94	100.00	99.94	111.25	111.25	111.25	111.25	111.25
100.00	74.95	75.00	111.25	111.25	111.25	111.25	111.25
75.00	49.94	50.00	111.25	111.25	111.25	111.25	111.25
50.00	24.94	25.00	111.25	111.25	111.25	111.25	111.25
25.00	0.00	0.00	111.25	111.25	111.25	111.25	111.25

Gas Sample Taken () Yes () No

H2S analysis done () Yes () No

H2O analysis done () Yes () No

2020/03/25 10:45:26

PHOTO 3: GAS METER CAL. REPORT

