

Inspection Photos

Location Name: LARAMIE ENERGY LLC Woods Spangler /15-13 Pad

Location ID: 334499



Photo #0813 from entrance to location



Photo #0814 Trash by tank battery.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Woods Spangler /15-13 Pad

Location ID: 334499



Photo #0815 Unused pipe stored on North end of location.