

Bonanza Creek Energy Operating, Inc.
Daily Completion/Workover Report

_____ New Drill _____ Recompletion **x** AFE _____ Re-Frac _____ Casing Repair _____ P&A

Date: **05-Mar-20** Well Name: **Latham 43-1** AFE / CO: _____

Legal Desc: **NESE**

Perforations	
Zone	Depths
CIBP	6140'
Niobrara	
A-Bench	6198' - 6204' (12 Holes)
B-Bench	6276' - 6288' (24 Holes)
C-Bench	6342' - 6348' (12 Holes)
Codell	6458' - 6466' (32 holes)

Sec: **1** Twn: **4N** Rng: **63W**

Surface Csg: 10 jts Size: **8 5/8"** Wt/Gd: **J-55** Conn. **8RD** Depth: **437'**

Production Csg: 155 jts Size: **4.5"** Wt/Gd: **11.6#** Conn. **LT&C** Depth: **6660'**

Rods: Size: _____ Wt/Gd: _____ Top: _____ Depth: _____

Tubing: 187 jts Size: **2 3/8"** Wt/Gd: **J-55** Conn. **8RD** Depth: **6062'**

Packer: _____ RBP: _____ CIBP **6140'** Sd Plug _____ Last Cleaned **6680'**

TD **7154'** PBTD **6660'** TOC _____ Out To _____

Fluid Lost **6470** Recovered **2123** Load Remaining **4347**

Other Information: _____

Job Objective: **Prep well for HZ frac**

Operation Past 24 Hours

3-5-2020
FCP-75, SITP-350
Brigade Rig #7, RU to blow well down, Rig was down a couple of hours to replace the stater on the rig. Control well with 60bbls water down casing and 20bbls down the tbg. TOOH 190 jnts to set CIBP at 6140', then covered with two sks. TIH with 187 jnts at, leaving 3 jnts out. EOT is at +/- 6062'. Rolled hole to clean and pressure tested to 1000 psi (good test) Rigged down to move in the morning. Turn well over to prod, end of report. Note: all expenses to be charged to the State North Platte T-36 & F-36 fracs.

Proposed Operations: **Turned over to production**

Supervisor: **Marty Krautschun**