

Location:	Whitehead 8-15
Line:	Well to Treater
Technicians:	Cody Baylis
Date	10/4/2019
Time	Pressure (PSI)
2:15:10 PM	0
2:15:40 PM	0
2:16:10 PM	0
2:16:40 PM	0
2:17:10 PM	0
2:17:40 PM	0
2:18:10 PM	65.1
2:18:40 PM	65.1
2:19:10 PM	65
2:19:40 PM	64.7
2:20:10 PM	64.8
2:20:40 PM	64.8
2:21:10 PM	64.8
2:21:40 PM	64.8
2:22:10 PM	64.8
2:22:40 PM	64.8
2:23:10 PM	64.8
2:23:40 PM	64.8
2:24:10 PM	64.8
2:24:40 PM	64.8
2:25:10 PM	64.8
2:25:40 PM	64.8
2:26:10 PM	64.8
2:26:40 PM	64.8
2:27:10 PM	64.8
2:27:40 PM	64.8
2:28:10 PM	64.8
2:28:40 PM	64.8
2:29:10 PM	64.8
2:29:40 PM	64.8
2:30:10 PM	64.8
2:30:40 PM	64.8
2:31:10 PM	64.8
2:31:40 PM	64.8
2:32:10 PM	64.8
2:32:40 PM	64.8
2:33:10 PM	64.8
2:33:40 PM	64.8
2:34:10 PM	64.8
2:34:40 PM	64.9
2:35:10 PM	64.9
2:35:40 PM	64.9

2:36:10 PM	64.9
2:36:40 PM	64.9
2:37:10 PM	64.9
2:37:40 PM	64.9
2:38:10 PM	64.9
2:38:40 PM	64.9
2:39:10 PM	64.9
2:39:40 PM	64.9
2:40:10 PM	64.9
2:40:40 PM	64.9
2:41:10 PM	65
2:41:40 PM	65
2:42:10 PM	65.1
2:42:40 PM	65.1
2:43:10 PM	65.1
2:43:40 PM	65.1
2:44:10 PM	65.1
2:44:40 PM	65.1
2:45:10 PM	65.1
2:45:40 PM	65.1
2:46:10 PM	65.1
2:46:40 PM	65.1
2:47:10 PM	65.1
2:47:40 PM	65.1
2:48:10 PM	65.1
2:48:40 PM	65.1
2:49:10 PM	65.1
2:49:40 PM	65.1
2:50:10 PM	65.1
2:50:40 PM	65.1
2:51:10 PM	65.1
2:51:40 PM	65.1
2:52:10 PM	65.2
2:52:40 PM	65.2
2:53:10 PM	65.2
2:53:40 PM	65.2
2:54:10 PM	0.9
2:54:40 PM	2.3
2:55:10 PM	3
2:55:40 PM	3.5

Pass/Fail

% loss over last 30 minutes	0.61%	Less than 10%	Yes		
% loss in last 5 minutes	0.15%	Less than 1%	Yes		Pass

