

Inspection Photos
Location Name: W H Coltharp 3
API: 05-103-40163



1: Digging out below GL on W H Coltharp 3 and removing cut off casing



2: Casing cut below GL with cement visible in casing at surface



Inspection Photos
Location Name: W H Coltharp 3
API: 05-103-40163



3: W H Coltharp 3 cap plate



4: Cap plate welded to casing below GL

Inspection Photos
Location Name: W H Coltharp 3
API: 05-103-40163



5: Well location filled in and marked with orange post for GPS reading

