

**Inspection Photos**  
**Location Name: RSU Anschutz Federal 4-62-2 PAD**  
**Location ID: 436165**



**Photo 1 – Wellheads**



**Photo 2 – Wellheads**

**Inspection Photos**  
**Location Name: RSU Anschutz Federal 4-62-2 PAD**  
**Location ID: 436165**




**Photo 3 – Tank Battery**



**Photo 4 – Unused Rods at Pumping Unit**



**Inspection Photos**  
**Location Name: RSU Anschutz Federal 4-62-2 PAD**  
**Location ID: 436165**



**Photo 5 – Unused Rods at Pumping Unit**




**Photo 6 – Unused Rods at Pumping Unit**



**Inspection Photos**  
**Location Name: RSU Anschutz Federal 4-62-2 PAD**  
**Location ID: 436165**



**Photo 7 – Unused platform north of Pumping Units**



**Photo 8 – Unused Wellhead parts at Pumping Unit**




## Inspection Photos

Location Name: RSU Anschutz Federal 4-62-2 PAD

Location ID: 436165




**Photo 9 – Containment not covered with Wildlife Netting**



**Photo 10 – Unmarked 1" Riser on the North side of Location**

**Inspection Photos**  
**Location Name: RSU Anschutz Federal 4-62-2 PAD**  
**Location ID: 436165**



**Photo 11 – Unmarked Risers on the North side of Location**