

Inspection Photos
Location Name: HSR-Guttersen 16-1
Location ID: 330448



Photo #1 Well & Sign

Photo #2 Variance Tag

Inspection Photos
Location Name: HSR-Guttersen 16-1
Location ID: 330448



Photo #3 Tank Battery



Photo #4 Separator, ECD & Meter Run

Inspection Photos
Location Name: HSR-Guttersen 16-1
Location ID: 330448



Photo #5 Leaking Master Valve "Gas"