

Inspection Photos
Location Name: Spaur 41-7 Pad
Location ID: 329435




Tank battery




Wellheads

Inspection Photos

Location Name: Spaur 41-7 Pad
Location ID: 329435



Meter calibration card on 2/19/2020



Meter calibration card on 3/26/2020