

Location:	CPC 569 E#1
Line:	Well to Treater
Technicians:	Cody Baylis
Date	10/3/2019
Time	Pressure (PSI)
4:15:00 PM	0.9
4:15:30 PM	0.9
4:16:00 PM	0.4
4:16:30 PM	0.4
4:17:00 PM	6.6
4:17:30 PM	35.9
4:18:00 PM	35.8
4:18:30 PM	36.1
4:19:00 PM	36
4:19:30 PM	36.1
4:20:00 PM	36.1
4:20:30 PM	36.1
4:21:00 PM	36.1
4:21:30 PM	36
4:22:00 PM	35.8
4:22:30 PM	35.1
4:23:00 PM	34.7
4:23:30 PM	35.2
4:24:00 PM	35.5
4:24:30 PM	35.5
4:25:00 PM	35.5
4:25:30 PM	35.3
4:26:00 PM	35.2
4:26:30 PM	35.2
4:27:00 PM	35.2
4:27:30 PM	35.3
4:28:00 PM	35.3
4:28:30 PM	35.4
4:29:00 PM	35.4
4:29:30 PM	35.3
4:30:00 PM	35.4
4:30:30 PM	35.4
4:31:00 PM	35.4
4:31:30 PM	35.5
4:32:00 PM	35.5
4:32:30 PM	35.5
4:33:00 PM	35.5
4:33:30 PM	35.5
4:34:00 PM	35.5
4:34:30 PM	35.6
4:35:00 PM	35.6
4:35:30 PM	35.6

4:36:00 PM	35.6
4:36:30 PM	35.7
4:37:00 PM	35.7
4:37:30 PM	35.7
4:38:00 PM	35.7
4:38:30 PM	35.7
4:39:00 PM	35.8
4:39:30 PM	35.8
4:40:00 PM	35.8
4:40:30 PM	35.8
4:41:00 PM	35.8
4:41:30 PM	35.9
4:42:00 PM	35.9
4:42:30 PM	35.9
4:43:00 PM	35.9
4:43:30 PM	35.9
4:44:00 PM	36
4:44:30 PM	36
4:45:00 PM	36
4:45:30 PM	36
4:46:00 PM	36.1
4:46:30 PM	36.1
4:47:00 PM	36.1
4:47:30 PM	36.1
4:48:00 PM	36.1
4:48:30 PM	36.1
4:49:00 PM	36.2
4:49:30 PM	36.2
4:50:00 PM	36.2
4:50:30 PM	36.2
4:51:00 PM	36.3
4:51:30 PM	37.6
4:52:00 PM	0.7
4:52:30 PM	0.7
4:53:00 PM	0.7
4:53:30 PM	0.7
4:54:00 PM	0.7
4:54:30 PM	0.7
4:55:00 PM	0.7

Pass/Fail

% loss over 30 minutes	3.88%	Less than 10%	Yes		
% loss in last 5 minutes	0.55%	Less than 1%	Yes		Pass

