

Location:	CPC 569 E#4
Line:	Well to Treater
Technicians:	Cody Baylis
Date	10/3/2019
Time	Pressure (PSI)
3:53:10 PM	0.1
3:53:40 PM	0
3:54:10 PM	3.2
3:54:40 PM	2.3
3:55:10 PM	0
3:55:40 PM	41.6
3:56:10 PM	41.6
3:56:40 PM	41.6
3:57:10 PM	41.6
3:57:40 PM	41.6
3:58:10 PM	41.6
3:58:40 PM	41.6
3:59:10 PM	41.6
3:59:40 PM	41.6
4:00:10 PM	41.6
4:00:40 PM	41.6
4:01:10 PM	41.6
4:01:40 PM	41.6
4:02:10 PM	41.6
4:02:40 PM	41.6
4:03:10 PM	41.6
4:03:40 PM	41.7
4:04:10 PM	41.7
4:04:40 PM	41.5
4:05:10 PM	41.4
4:05:40 PM	41.5
4:06:10 PM	41.5
4:06:40 PM	41.4
4:07:10 PM	41.5
4:07:40 PM	41.5
4:08:10 PM	41.5
4:08:40 PM	41.4
4:09:10 PM	41.5
4:09:40 PM	41.5
4:10:10 PM	41.5
4:10:40 PM	41.5
4:11:10 PM	41.5
4:11:40 PM	41.4
4:12:10 PM	41.5
4:12:40 PM	41.4
4:13:10 PM	41.4
4:13:40 PM	41.4

4:14:10 PM	41.4
4:14:40 PM	41.4
4:15:10 PM	41.4
4:15:40 PM	41.4
4:16:10 PM	41.4
4:16:40 PM	41.4
4:17:10 PM	41.4
4:17:40 PM	41.3
4:18:10 PM	41.4
4:18:40 PM	41.4
4:19:10 PM	41.3
4:19:40 PM	41.3
4:20:10 PM	41.3
4:20:40 PM	41.3
4:21:10 PM	41.3
4:21:40 PM	41.3
4:22:10 PM	41.3
4:22:40 PM	41.3
4:23:10 PM	41.3
4:23:40 PM	41.3
4:24:10 PM	41.3
4:24:40 PM	41.3
4:25:10 PM	41.3
4:25:40 PM	41.2
4:26:10 PM	41.3
4:26:40 PM	41.3
4:27:10 PM	41.3
4:27:40 PM	41.3
4:28:10 PM	41.2
4:28:40 PM	41.2
4:29:10 PM	41.3
4:29:40 PM	0
4:30:10 PM	0
4:30:40 PM	0
4:31:10 PM	0
4:31:40 PM	0.1
4:32:10 PM	0.2

Pass/Fail

% loss over 30 minutes	0.96%	Less than 10%	Yes		
% loss in last 5 minutes	0.24%	Less than 1%	Yes		Pass

