

Location:	CPC 569 E#5
Line:	Well to Treater
Technicians:	Cody Baylis
Date	10/4/2019
Time	Pressure (PSI)
12:13:10 PM	7.6
12:13:40 PM	7.6
12:14:10 PM	7.6
12:14:40 PM	7.6
12:15:10 PM	7.6
12:15:40 PM	7.6
12:16:10 PM	7.6
12:16:40 PM	23.6
12:17:10 PM	23.6
12:17:40 PM	23.6
12:18:10 PM	23.5
12:18:40 PM	23.5
12:19:10 PM	23.5
12:19:40 PM	23.5
12:20:10 PM	23.4
12:20:40 PM	23.4
12:21:10 PM	23.4
12:21:40 PM	23.4
12:22:10 PM	23.4
12:22:40 PM	23.3
12:23:10 PM	23.3
12:23:40 PM	23.3
12:24:10 PM	23.3
12:24:40 PM	23.2
12:25:10 PM	23.2
12:25:40 PM	23.2
12:26:10 PM	23.2
12:26:40 PM	23.2
12:27:10 PM	23.1
12:27:40 PM	23.1
12:28:10 PM	23.1
12:28:40 PM	23
12:29:10 PM	23
12:29:40 PM	23
12:30:10 PM	22.9
12:30:40 PM	22.9
12:31:10 PM	22.9
12:31:40 PM	22.9
12:32:10 PM	22.8
12:32:40 PM	22.8
12:33:10 PM	22.8
12:33:40 PM	22.8

12:34:10 PM	22.8
12:34:40 PM	22.8
12:35:10 PM	22.7
12:35:40 PM	22.7
12:36:10 PM	22.7
12:36:40 PM	22.7
12:37:10 PM	22.6
12:37:40 PM	22.6
12:38:10 PM	22.6
12:38:40 PM	22.5
12:39:10 PM	22.5
12:39:40 PM	22.5
12:40:10 PM	22.4
12:40:40 PM	22.4
12:41:10 PM	22.4
12:41:40 PM	22.4
12:42:10 PM	22.3
12:42:40 PM	22.3
12:43:10 PM	22.3
12:43:40 PM	22.3
12:44:10 PM	22.2
12:44:40 PM	22.2
12:45:10 PM	22.2
12:45:40 PM	22.2
12:46:10 PM	22.2
12:46:40 PM	22.2
12:47:10 PM	22.2
12:47:40 PM	22.2
12:48:10 PM	22.2
12:48:40 PM	0
12:49:10 PM	0
12:49:40 PM	0
12:50:10 PM	0
12:50:40 PM	0

Pass/Fail

% loss over 30 minutes	5.93%	Less than 10%	Yes		
% loss in last 5 minutes	0.45%	Less than 1%	Yes		Pass

