


| | |
|--------------|-----------------|
| Location: | Whitehead 12-7 |
| Line: | Well to Treater |
| Technicians: | Cody Baylis |
| Date | 10/4/2019 |
| Time | Pressure (PSI) |
| 3:25:10 PM | 5.5 |
| 3:25:40 PM | 5.5 |
| 3:26:10 PM | 5.5 |
| 3:26:40 PM | 0 |
| 3:27:10 PM | 61.7 |
| 3:27:40 PM | 61.3 |
| 3:28:10 PM | 60.8 |
| 3:28:40 PM | 60.6 |
| 3:29:10 PM | 60.4 |
| 3:29:40 PM | 60.2 |
| 3:30:10 PM | 59.9 |
| 3:30:40 PM | 59.7 |
| 3:31:10 PM | 59.5 |
| 3:31:40 PM | 59.3 |
| 3:32:10 PM | 59.2 |
| 3:32:40 PM | 59 |
| 3:33:10 PM | 58.8 |
| 3:33:40 PM | 58.6 |
| 3:34:10 PM | 58.5 |
| 3:34:40 PM | 58.3 |
| 3:35:10 PM | 58.2 |
| 3:35:40 PM | 58 |
| 3:36:10 PM | 57.8 |
| 3:36:40 PM | 57.7 |
| 3:37:10 PM | 57.6 |
| 3:37:40 PM | 57.4 |
| 3:38:10 PM | 57.3 |
| 3:38:40 PM | 57.1 |
| 3:39:10 PM | 57 |
| 3:39:40 PM | 56.9 |
| 3:40:10 PM | 56.7 |
| 3:40:40 PM | 56.6 |
| 3:41:10 PM | 56.4 |
| 3:41:40 PM | 56.3 |
| 3:42:10 PM | 56.2 |
| 3:42:40 PM | 56.1 |
| 3:43:10 PM | 55.9 |
| 3:43:40 PM | 55.8 |
| 3:44:10 PM | 55.6 |
| 3:44:40 PM | 55.6 |
| 3:45:10 PM | 55.2 |
| 3:45:40 PM | 54.7 |

| | |
|------------|------|
| 3:46:10 PM | 54.4 |
| 3:46:40 PM | 54.4 |
| 3:47:10 PM | 54.1 |
| 3:47:40 PM | 54 |
| 3:48:10 PM | 54 |
| 3:48:40 PM | 54 |
| 3:49:10 PM | 54 |
| 3:49:40 PM | 54.1 |
| 3:50:10 PM | 54.1 |
| 3:50:40 PM | 54.2 |
| 3:51:10 PM | 54.3 |
| 3:51:40 PM | 54.4 |
| 3:52:10 PM | 54.6 |
| 3:52:40 PM | 54.6 |
| 3:53:10 PM | 54.7 |
| 3:53:40 PM | 54.8 |
| 3:54:10 PM | 54.8 |
| 3:54:40 PM | 54.9 |
| 3:55:10 PM | 54.9 |
| 3:55:40 PM | 54.9 |
| 3:56:10 PM | 54.9 |
| 3:56:40 PM | 54.9 |
| 3:57:10 PM | 54.9 |
| 3:57:40 PM | 54.9 |
| 3:58:10 PM | 55 |
| 3:58:40 PM | 54.9 |
| 3:59:10 PM | 54.9 |
| 3:59:40 PM | 54.9 |
| 4:00:10 PM | 54.9 |
| 4:00:40 PM | 54.9 |
| 4:01:10 PM | 54.9 |
| 4:01:40 PM | 54.9 |
| 4:02:10 PM | 54.9 |
| 4:02:40 PM | 54.9 |
| 4:03:10 PM | 54.9 |
| 4:03:40 PM | 54.9 |
| 4:04:10 PM | 54.9 |
| 4:04:40 PM | 54.9 |
| 4:05:10 PM | 54.9 |
| 4:05:40 PM | 54.9 |
| 4:06:10 PM | 54.9 |
| 4:06:40 PM | 54.9 |
| 4:07:10 PM | 54.8 |
| 4:07:40 PM | 54.8 |
| 4:08:10 PM | 54.8 |
| 4:08:40 PM | 54.8 |
| 4:09:10 PM | 54.8 |

| | |
|------------|------|
| 4:09:40 PM | 54.8 |
| 4:10:10 PM | 54.8 |
| 4:10:40 PM | 54.8 |
| 4:11:10 PM | 54.8 |
| 4:11:40 PM | 54.8 |
| 4:12:10 PM | 54.8 |
| 4:12:40 PM | 54.7 |
| 4:13:10 PM | 54.7 |
| 4:13:40 PM | 54.7 |
| 4:14:10 PM | 54.7 |
| 4:14:40 PM | 54.7 |
| 4:15:10 PM | 54.7 |
| 4:15:40 PM | 54.7 |
| 4:16:10 PM | 54.7 |
| 4:16:40 PM | 54.6 |
| 4:17:10 PM | 54.6 |
| 4:17:40 PM | 54.6 |
| 4:18:10 PM | 54.6 |
| 4:18:40 PM | 54.6 |
| 4:19:10 PM | 54.6 |
| 4:19:40 PM | 54.5 |
| 4:20:10 PM | 54.5 |
| 4:20:40 PM | 0.1 |
| 4:21:10 PM | 0 |
| 4:21:40 PM | 0 |
| 4:22:10 PM | 0 |
| 4:22:40 PM | 0 |

Pass/Fail

| | | | | | |
|--------------------------|-------|---------------|-----|--|------|
| % loss over 30 minutes | 2.17% | Less than 10% | Yes | | |
| % loss in last 5 minutes | 0.37% | Less than 1% | Yes | | Pass |



Found and repaired leaking valve in middle of test