

Inspection Photos

API: 071-08043

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/25/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08043 | Date: 3/25/2020

Inspection Photos



Photo 1. Rock rip/rap has been installed along the lease road as it ascends the hill.



Inspection Photos



Photo 2. Facing west along the lease road. Rock rip/rap has been installed along the lease road as it descends the hill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08043 | Date: 3/25/2020

Inspection Photos



Photo 3. Culvert outlet protection and a rock sediment trap have been installed in drainage area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08043 | Date: 3/25/2020

Inspection Photos



Photo 4. Maintenance has been performed on the gates near the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08043 | Date: 3/25/2020

Inspection Photos



Photo 5. Facing toward the location.



Inspection Photos



Photo 6. The well sign is posted at the meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08043 | Date: 3/25/2020