

Inspection Photos

API: 071-07803

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/25/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07803 | Date: 3/25/2020

Inspection Photos



Photo 1. Facing toward culvert outlet along main lease road. Outlet protection has been installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07803 | Date: 3/25/2020

Inspection Photos



Photo 2. Facing southwest along the main lease road. Rock check dams have been installed along the road in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07803 | Date: 3/25/2020

Inspection Photos



Photo 3. Outlet protection has been installed where erosion was observed at culvert outlet.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07803 | Date: 3/25/2020

Inspection Photos



Photo 4. The erosion along the side of the lease road has been repaired and stabilized with rock rip/rap.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07803 | Date: 3/25/2020

Inspection Photos



Photo 5. Culvert outlet protection has been installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07803 | Date: 3/25/2020

Inspection Photos



Photo 6. Culvert outlet protection has been installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07803 | Date: 3/25/2020

Inspection Photos



Photo 7. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07803 | Date: 3/25/2020

Inspection Photos



Photo 5. Well sign is posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07803 | Date: 3/25/2020